# **Components**

Connector Socket AT04-12PA



Connector Socket Wedge AW12P



Male Pin (Crimped on wire) Contact Size 16 AT60-202-16141




### **Process**



 Grasp contact approximately 1.0" behind contact barrel.



2. Hold connector with rear grommet facing you.



3. Push contact straight into connector grommet until a click is felt. A slight tug will confirm that it is locked in place.



## **Process**



4. Once all contacts are in place, insert wedge. The wedge will snap into place.



### **Tools**

**Retention Tester** HT250-5



**Socket Tester Contact Size 16** 67-016-01



**Pin Tester Contact Size 16** 68-016-01



### **Process**

1. Insert tester into mating end of contact. Tool must be in a straight line with contact.



2. Apply pressure toward contact until slide aligns with indicator line. **Contact should** remain in place.





